


832006


FCC ID: H79DB-995

Reference modification letter: No.4



832006


FCC ID: H79DB-995
Reference modification letter: No.4,5



832006

FCC ID: H79DB-995

Reference modification letter: No.4,5




832006

FCC ID: H79DB-995
Reference modification letter: No.6

8




FCC ID: H79DB-995
Reference modification letter: No.7



FCC ID: H79DB-995
Mechanical construction


832006



832006

FCC ID: H79DB-995
Mechanical construction

11




832006

FCC ID: H79DB-995
Mechanical construction

832006

FCC ID: H79DB-995
Mechanical construction




832006



FCC ID: H79DB-995


Reference modification letter No.: 6,21



832006

FCC ID: H79DB-995

Reference modification letter: No. 6, 8, 9, 10



FCC ID: H79DB-995
Mechanical construction

16

13 ↑

14 ↗

11 ↑

832006

FCC ID: H79DB-995

Reference modification letter: No. 11,12,13

17



832006

FCC ID: H79DB-995
Reference modification letter: No.20

18

832006


FCC ID: H79DB-995
Mechanical construction



FCC ID: H79DB-995
Reference modification letter: No.14,15,16


832006






832006

FCC ID: H79DB-995
Rear side of main board & CRT board
Reference modification letter: No. 17, 19




832006



FCC ID: H79DB-995
Reference modification letter: No.18



832006



FCC ID: H79DB-995




Mechanical construction

832006



FCC ID: H79DB-995
Mechanical construction




832006



FCC ID: H79DB-995

Front side of Function & Input board

832006



FCC ID: H79DB-995
 Rear side of Function & Input board
 Reference modification letter: No.17