FccID: H9PNP4046

Conf Num: EA99556

DS NetVision® Phone Original Equip.

Corespondence # 19611 Date Emailed: 6/13/01

Question 1

The request for change in FCC identifier must

be submitted in the filing.

Ouestion 2

The label must be corrected and submitted.

Question 3

The the SAR report lists the "Stick on" antenna as 0 dBi while the latest exhibit lists it as 2 dBi.

Question 4

Indicate whether the device transmits simultaneously on both antennas when the "Stick on" antenna is installed.

Ouestion 5

The RF safety needs revision. Remove the word Warning. Since SAR was tested, revise the statements to include only the following To comply with RF safety requrirements use the specific belt clip. All other belt clips should be avoided and may not comply with RF safety requirements.

Answer:

Please change the FCC identifier from H9PDM4046 to H9PNP4046.

Answer:

Please see the uploaded corrected label.

Answer:

The SAR report is incorrect. The correct gain for the "Stick on" antenna is 2 dBi.

Answer:

The device only transmits on one antenna at a time.

Answer:

Please see the uploaded revised Regulatory Addendum.