

February 19, 2009

TIMCO ENGINEERING INC  
849 NW State Road 45  
Newberry, Florida 32669

**Subject: FCC ID: IA9OEM900MR**  
**Reference: Job 324UC9**

Dear Sir or Madam:

As per your finding e-mail dated February 19, 2009, please see below:

1. The 731 form is missing item #13 on the form. Please re-submit
  - a. Please find attached revised 731 form as per your request.
2. Please provide a complete statement of the changes including any characteristics affected by the change.
  - a. The following changes/modification have been made to the schematic:
    - i. On U403, "STR912FW44X6" was replaced with "STR912FAW44X6"
    - ii. Changed value for C258 to part #C0294.
  - b. The changes only increased the performance.
  - c. The changes did not effect any FCC or Industry Canada requirements.

If you have any questions please feel free to contact the undersigned.

Sincerely,

Radu Oprea