



**MOTOROLA**

**Date:** December 18, 2003

**Subject:** Request for additional information regarding FCC ID: IHDT5DY1 (Portable Cellular AMPS/CDMA transceiver)

**Reference:**

Application Received:	12/5/2003
Correspondence Reference Number:	231211B.IHD
Confirmation Number:	TC3314
Date of Original Email:	12/11/2003

**Prepared by:**

Andrew Bachler, Principal Staff Engineer  
Motorola Personal Communications Sector  
Libertyville, Illinois

**Questions and responses follow:**

1. The Specification Compliance Statement is insufficient. Section 22.901(e)(1) requires that a statement be submitted that confirms compliance with ANSI TIA/EIA 553-A-1999. In addition, we note that an incorrect FCC ID is listed in the existing statement- this should be corrected to the FCC of the EUT.

**Response:** The attestation statements have been revised. Please refer to the replacement exhibit 2 (Attestation Statements) submitted on 12/18/03.

2. There is a discrepancy between the measured ERP levels listed at the top of p.10 of the EMC report and the values listed in the Summary at the bottom of that page. Please address.

**Response:** The radiated power levels in the test report have been corrected. Please refer to the replacement exhibit 6 (Test Report) submitted on 12/18/03.

3. Please submit the following Exhibits: Block Diagram (#4) and Operational Description (#12).

**Response:** Exhibit 4 and exhibit 12 were submitted on 12/9/03.