

Response to E04-000085-1

1. 78kHz clock is used in the digital circuitry only and is not associated with the transmitter, therefore testing below 14MHz is not required.
2. All tables and data sheets have correction factors. What pages are you referring to?
3. A revised users manual has been uploaded.
4. Our device 6312/6328 is one way system without feedback, it can not and will not adjust its hop table to avoid interference.
5. A revised label has been uploaded.