

## **Description of Changes in the Trimmark 3b:**

### Changes in the Digital RF board

- The Synthesizer chip was changed for an equivalent part because the original one became obsolete.

### Changes in the Power Amplifier (PA) board

- The 25W PA Module (U4) was changed for an equivalent part because the original one became obsolete;
- Also, the Driver (U10) chip was changed for the same reason.