

-----Original Message-----

From: ellis@adt.com.tw [mailto:ellis@adt.com.tw]

Sent: Wednesday, December 10, 2003 10:51 PM

To: smiler@adt.com.tw; dward

Cc: stephanie@adt.com.tw

Subject: |^«H: Âà±H;G FCC ID: JVP56W10

Dennis,

The software control is provided to the EUT and it can NOT transmit at the same time, i think ATCB can review it. Would you confrim again.

Due to it is an urgent case, will you follow up soon.

Thanks.

Best Regards.

吳佳鑫 / Ellis Wu

E-mail : Ellis@ADT.COM.TW

誠信科技 / ADT Corp.

TEL : +886 3 3270910 #1624

FAX : +886 3 3270892

Dear Dennis:

Here are the answer from our client.

"The software program has been built into the reflash/RAM inside on transmitting and the user can't access to it anyway. All setting -up procedure has done and completed on production. So far,the users can't authorize to change the features of device even simultaneous transmission. We agree with ADT finding the simultaneous transmission,but we could provide another EUT whose reflash/RAM having a new one software program to fill it. BTW,the next project has to go immediately as the above mentioned. this new FCC ID is JVP56W10A. All relating documents required is same as FCC ID :56W10 ,reviewed by FCC.

Regards.

James"

Best Regards,  
Stephanie Hung (洪樹薇)  
Advance Data Technology Corporation (誠信科技)  
Website: [www.adt.com.tw](http://www.adt.com.tw)  
Tel: 886-3 327 0910 Ext. 1668  
Fax: 886-3 327 0892  
e-mail: [stephanie@adt.com.tw](mailto:stephanie@adt.com.tw)