
Description of Permissive Change

This report is prepared for FCC class II permissive change. The difference compared with the original design listed as below:

ITEM	CLASS II CHANGE DESCRIPTION
1	Remove fuse for over-current protection at power jack
2	Add common mode choke at RJ-11

Item 1

Original



Fuse removed



Report No.: RF970819L04A


FCC ID: K7SF5D8635-4A

Item 2

Original



Add common mode choke



Report No.: RF970819L04A