



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 26, 2004

RE: D-Link Corporation

FCC ID: KA2DI624SA1

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The POA is not dated. Please revise.
- 2) A modular request letter does not appear to have been provided but it appears applicable to this device. Please explain/ provide as necessary.
- 3) The power measurements for modes A and B are exactly identical. It appears that both modes were not fully tested or the data is not correct. I find it difficult to believe the data can be exactly identical for both modes. Just the measurement tolerances would show different results between these 2 modes. Please review/correct as necessary.
- 4) The spectral density plot for Turbo mode appears to be missing from the report. Please provide.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.