



Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
Phone: 408-526-4000  
Fax: 408-526-4100  
<http://www.cisco.com>

**Tune-up Procedure**

Date: May. 29. 2018

Subject: FCC ID: LDK06131817

The RF module and hardware PCB is designed to meet FCC requirements. The maximal output power for all transceivers is fixed by firmware and cannot be changed by the user either through software upgrades or any other means.

Sincerely,

A handwritten signature in black ink that reads "Torbjorn Sundsvaen".

By:

Engineer, Mechanical Engineering  
(Signature/Title)

Torbjorn Sundsvaen  
(Print name)