

Cisco Systems, Inc. 4125 Highlander Parkway Richfield, Ohio 44286 Phone: 330 523-2094 Fax: 330 523-2002 http://www.cisco.com

August 21, 2006

Federal Communications Commission 7435 Oakland Mills Road Columbia MD 21046

 Subject:
 CRN 31391 Reply

 FCC ID:
 LDK102053 (EA826475)

To Whom It May Concern:

Question 1) Please explain/describe collocated transmitting modes of this device, including associated FCC ID(s) if applicable. Please describe testing done per 15.31h,k, and explain why if data not submitted.

Response: This device can be collocated with FCC ID LDK102049. The test results covering 15.31h and k were covered in the test report for the original submittal.

Best Regards,

Jim Nicholson EMC Compliance Engineer