



Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
Phone: 408-526-4000
Fax: 408-526-4100
<http://www.cisco.com>

Tune-up Procedure

Date: Dec. 13, 2016

Subject: FCC ID: LDK7-23-1377

The RF module and hardware PCB is designed to meet FCC requirements. The maximal output power for all transceivers is fixed by firmware and cannot be changed by the user either through software upgrades or any other means.