





Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
Phone 408 526-4000
Fax: 408 526 -4100
<http://www.cisco.com>


Exhibit : Internal Photos


Model Number: CP-DX70
FCC ID: LDKDX700976
IC: 2461B – DX700976





: Internal antenna connection








AMPHENOL 4878

TB 0314

AMPHENOL 4878
TB 0314







SIDE BOARD





LAFAYETTE SIDE BOARD
1444830001
10/14 CAV 24


MAIN BOARD

31205AC

AP112

D1 470E UD






P1
S25176A2
[B01]-L2

94V-0 GW-05
E187088

2L


1413-3



73-16271-03 02 +
SN: FOC1814NEJ2

14 ©

AB





P1
S25176A2
-[B0]-L2

94V-0 GW-05 ▲
E187088

2L

1413-3

S25176A2-0320



FAY-IEA0
SN:TYZ18070232

