




Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
Phone 408 526-4000  
Fax: 408 526 -4100  
<http://www.cisco.com>

Exhibit : Internal Photos


Model Number: CP-DX80  
FCC ID: LDKDX800956  
IC: 2461B - DX800956

CP-DX80 : Internal PCB Mother Board (top view)




EDCS-1118876

CP-DX80 : Internal PCB Mother Board (Connector view)






CP-DX80 : Internal PCB Mother Board (Radio Section with Shield removed)




Radio Section

CP-DX80 : Internal PCB Mother Board (Top 1/3) close up view






CP-DX80 : Internal PCB Mother Board (Top 2/3) close up view




CP-DX80 : Internal PCB Mother Board (Top 3/3) close up view





CP-DX80 : Internal PCB Mother Board (bottom view)



CP-DX80 : Internal PCB Mother Board (bottom 1/3) Close up view

