

June 10, 2005

American TCB 6731 Whittier Ave. Suite C110 McLean, VA 22101

Attn: Director of Certification

guan man-

This letter is to notify that the radio model: U58H068, FCC ID: LDKXSCLCR14 has no field hardware adjustments points. All configuration changes possible are made via software, and are described in the Cisco Configuration manual for this equipment. Therefore, no tune-up procedure is submitted for the equipment.

Regards,

Juan Martinez

Sr. EMC Engineer