



To whom it may concern

Ljiljana Trivic

Certification Responsible

E-Mail: Ljiljana.Trivic@Aptiv.com

Phone +49 2261 971 415

Date: 24t June 2020

Compliance Statement in Car Manual / FCC ID: LTQFI7

Dear Sirs,

We APTIV hereby declare, that the IBCM device is installed inside transportation vehicles. The overall operation/function will be described inside the individual manual of the vehicle.

The below listed statements will be therefore additionally included:

USA Model: FI7

FCC ID : LTQFI7

"CAUTION TO USERS"

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

This device complies with Part 15 of the FCC Rules and with RSS of the Industry Canada. Operation is subject to the following two conditions:

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation.

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the

Aptiv Services Deutschland GmbH

Postanschrift:
D-42367 Wuppertal

Hausanschrift:
Am Technologiepark 1
D-42119 Wuppertal

Telefon: (02 02) 2 91 - 0
Telefax: (02 02) 2 91 - 2777
Internet: www.aptiv.com

Sitz der Gesellschaft:
Wuppertal
Registergericht: AG Wuppertal,
HRB 21453

Geschäftsführung:
Kirsten Stenvers (Sprecherin)
Matthias Laumann

Aufsichtsrat:
Michael Gassen
(Vorsitzender)

• APTIV •

equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Yours Sincerely


STC
STC Germany GmbH
Ohnhäuserstr. 1
44160 Fronhausen

Anton Tropschmann

STC Germany GmbH

Head of Laboratory

(Authorized Agent)

Aptiv Services Deutschland GmbH

Postanschrift:
D-42367 Wuppertal

Hausanschrift:
Am Technologiepark 1
D-42119 Wuppertal

Telefon: (02 02) 2 91 - 0
Telefax: (02 02) 2 91 - 2777
Internet: www.aptiv.com

Sitz der Gesellschaft:
Wuppertal
Registergericht: AG Wuppertal,
HRB 21453

Geschäftsführung:
Kirsten Stenvers (Sprecherin)
Matthias Laumann

Aufsichtsrat:
Michael Gassen
(Vorsitzender)