

Attestation from Applicant

Type of equipment tested: Pre-production

Modifications made during testing that are required for FCC compliance and will be incorporated into all production units:
A single one-turn ferrite was added to all the external I/O cables together. This ferrite was later mounted internally on the portion of the cables that normally reside within the device enclosure.

The small two-turn ferrite was removed from the cable connecting the card reader to the motherboard, and replaced by a larger two-turn ferrite at the opposite end of the cable.

Description of the software and firmware used to operate the radio, including name and revision level:

MorphoAccess firmware version 4.42, consisting of the following files:

dbiorom_4.42.edb
static_kernel_4.42.edb
spilv_4.42.edb
maccess_4.42.edb
langue0.bin
langue1.bin
langue2.bin

ACG H102014BC firmware version 0.14e