Untertuerkheimer Str. 6-10, 66117 Saarbruecken, Germany Phone: +49 (0) 681 598-0 SAR-Laboratory

Phone: +49 (0) 681 598-8454

Fax: -8475





Accredited testing laboratory

DAR registration number: TTI-P-G 166/98

Federal Motor Transport Authority (KBA) DAR registration number: KBA-P 00070-97

Appendix to the Report 2-3078-1-3/02 **Photo documentation**

As of September 20, 2002 Page 1 of 30 Photo documentation Report No.: 2-3078-1-3/02



Annex 3 Photo documentation

Picture no. 1

Measurement System DASY 3



As of September 20, 2002 Page 2 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 2

E2002p front touch left



As of September 20, 2002 Page 3 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 3

E2002p rear touch left



As of September 20, 2002 Page 4 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 4

E2002p side touch left



As of September 20, 2002 Page 5 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 5

E2002p front tilted left



As of September 20, 2002 Page 6 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 6

E2002p side tilted left



As of September 20, 2002 Page 7 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 7

E2002p front tilted left




As of September 20, 2002 Page 8 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 8

E2002p front touch right




As of September 20, 2002 Page 9 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 9

E2002p side touch right




As of September 20, 2002 Page 10 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 10

E2002p rear touch right




As of September 20, 2002 Page 11 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 11

E2002p front tilted right




As of September 20, 2002 Page 12 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 12

E2002p side tilted right



As of September 20, 2002 Page 13 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 13

E2002p rear tilted right




As of September 20, 2002 Page 14 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 14

E2002p flat front 15mm



As of September 20, 2002 Page 15 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 15

E2002p flat front 15mm




As of September 20, 2002 Page 16 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 16

E2002p flat front 15mm




As of September 20, 2002 Page 17 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 17

E2002p flat rear 15mm




As of September 20, 2002 Page 18 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 18

E2002p flat rear 15mm



As of September 20, 2002 Page 19 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 19

E2002p flat rear 15mm



As of September 20, 2002 Page 20 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 20

E2002p front



As of September 20, 2002 Page 21 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 21

E2002p left side



As of September 20, 2002 Page 22 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 22

E2002p rear side with battery



As of September 20, 2002 Page 23 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 23

E2002p rear side without battery



As of September 20, 2002 Page 24 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 24

E2002p rear side



As of September 20, 2002 Page 25 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 25

E2002p left side



As of September 20, 2002 Page 26 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 26

battery front



As of September 20, 2002 Page 27 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 27

battery rear




As of September 20, 2002 Page 28 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 28

liquid depth head 1900 MHz



As of September 20, 2002 Page 29 of 30

Photo documentation Report No.: 2-3078-1-3/02



Picture no. 29

liquid depth body 1900 MHz



As of September 20, 2002 Page 30 of 30