13. SETUP PHOTOS



LINE CONDUCTED FRONT PHOTO

LINE CONDUCTED SIDE VIEW PHOTO


Page 131 of 137



END OF REPORT


Page 132 of 137

14. EUT PHOTOS




UL VERIFICATION SERVICES INC. 47173 BENICIA STREET, FREMONT, CA 94538, USA This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.


Page 133 of 137




Page 134 of 137



Page 135 of 137



Page 136 of 137



END OF REPORT

Page 137 of 137