



Comcast DTA RF4CE 2 Device URC-4067
FCC ID: MG3-4067

Below are the modifications that were found to be necessary for compliance.

List of modifications:

C17 in RF transmitter Antenna1 section was DNF (Do Not Fit), now 0.5pF

C10 in RF transmitter Antenna2 section was 2.2pF, now 1,8pF

C17 in RF transmitter Antenna2 section was 2.2pF, now 1.8pF

The output power on the RF chip was changed from 0dBm, to -4.0 dBm.

If you have any questions or need additional information, please contact the undersigned at (714) 820-1094.

Regards,

A handwritten signature in black ink, appearing to read "Jesse Mendez", is written over a thin horizontal line.

Jesse Mendez

Sr. Electrical Core Engineer