

May 9, 2012

Equipment Authorization Branch
Laboratory Division
Office of Engineering and Technology
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Gentlemen:

During the course of filing the system application, an FCC ID for the external device was changed from MHATRXDSI to MHATRUTRX. Since the filing is for a system consisting of an implanted and associated external transceiver, the manual has been changed to delete any reference to the incorrect FCC ID. A replacement FCC ID label info is filed. The filed agent authorization letter is also being updated.

Sincerely yours,

A handwritten signature in cursive script, appearing to read "Phillip Inglis".

Phillip Inglis
TRP Inc.