


November 9, 2009

Bay Area Compliance Laboratory (BACL)

RE: changes to the circuit of Midland Radio Corporation model CB Module FCC ID: MMA77321


The PLL integrated circuit which determines the operating frequency has been changed due to component availability problem. Only the U8 component in has changed, no PCB layout changes were made.

New circuit





Old circuit



Please accept this as a permissive change.

David K, Free, Engineering Project Manager

Midland Radio Corporation

David K. tun