Report No: 15081213HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)




Report No: 15081213HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Back View)




Report No: 15081213HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)




Report No: 15081213HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Back View)



Report No: 15081213HKG-001

Configuration Photographs

Worst-Case Conducted Emissions

(Front View)




Report No: 15081213HKG-001

Configuration Photographs

Worst-Case Conducted Emissions

(Right View)



Report No: 15081213HKG-001

Configuration Photographs

Worst-Case Conducted Emissions

(Left View)

