

Output is EIRP. Device operates with an internal antenna.

The differences in EIRP are caused by an error in the test-equipment. The revised EIRP (27,4/27,7) are obtained through new measurements on the same phones – but with new test equipment. The EIRP differences are not caused by any changes in the phones and have therefore no effect on the measured SAR values. Regarding differences between flat phantom and cheek position SAR values, we have experienced this on other phones, it is nothing unusual.