



56043255XX



DAIMLERCHRYSLER PCL: TBD

PROD. DATE/SHIFT: 3423/1

MAIN S/W REV: 4.8.0 H/W REV: 000A 75813

FCC ID: NT8UCON2



IC: 3043A-UCON2

VS9832C000YA

VISTEON CORPORATION

DRS

!!! WARNING !!!

Any modifications/analysis done to this part **MUST** be recorded in:

k:\PLUS\11830-05PA\electronics\engineering\parts record.xls

Failure to comply compromises the ability to root cause issues,
leading to significant project delays and wasted time.

OSPA
4.8.0#9
J1050
Plain



05091004XX



DAIMLERCHRYSLER PCL: TBD
PROD. DATE/SHIFT: 3423/1
MAIN S/W REV: 4.8.0 H/W REV: 000A 75813
FCC ID: TBD
IC: TBD



VS9830C003ZA



!!! WARNING !!!

Any modifications/analysis done to this part **MUST** be recorded in:
k:\PLUS\1830-05PA\electronics\engineering\parts record.xls
Failure to comply compromises the ability to root cause issues,
leading to significant project delays and wasted time.



CHN



05064013XX



DAIMLERCHRYSLER PCL: TBD
PROD. DATE/SHIFT: 3283/2
MAIN S/W REV: 4.8.0 H/W REV: 000A 75813
BUS S/W REV: 1.0
FCC ID: NT8UCON2
IC: 3043A-UCON2 VS8734C0014A



VISTEON CORPORATION

!!! WARNING !!!

Any modifications/analysis done to this part **MUST** be recorded in:
k:\PLUS\1830-05PA\electronics\engineering\parts record.xls
Failure to comply compromises the ability to root cause issues,
leading to significant project delays and wasted time.

