

## Coverletter:

Submitting of requested information for FCC-ID: NXWMOBYU-MDSU589

List of documents:

<b>Question</b>	<b>Theme</b>	<b>Response</b>
1	Field strength in grant	Removed
2	Equipment class	Corrected
3	Label	Corrected in file: MDS 589.pdf
4	Letter requesting confidentiality	Corrected in file: REQUEST FOR CONFIDENTIALITY.doc
5	Internal photos	No more applicable
6	Testing on three frequencies	See test report-file: 03-103.pdf and setup03-103.pdf for photos
7	Measurement to the 10 <sup>th</sup> harmonic	See test report-file: 03-103.pdf and setup03-103.pdf for photos
<b>8</b>	<b>Antenna requirement according to 15.203</b>	<b>The Antenna(e) are permanently attached to the PCB by soldering.</b>
9	Peak values	See test report-file: 03-103.pdf and setup03-103.pdf for photos
10	Separate tests and reports	See test report-file: 03-103.pdf and setup03-103.pdf for photos
11	Test signal	See test report-file: 03-103.pdf and setup03-103.pdf for photos
12	Identical files	corrected

Additional information to the user manual: Beiblatt\_Manual.doc