



**Photograph 50: Radiated Emissions – TC #1; Fiberglass Container, Rear View**




**Photograph 51: Radiated Emissions – TC #2; Fiberglass Container, Front View**






**Photograph 52: Radiated Emissions – TC #2; Fiberglass Container, Rear View**




**Photograph 53: Radiated Emissions – TC #3; Fiberglass Container, Front View**





**Photograph 54: Radiated Emissions – TC #3; Fiberglass Container, Rear View**



**Photograph 55: Radiated Emissions – TC #4; Fiberglass Container, Front View**






**Photograph 56: Radiated Emissions – TC #4; Fiberglass Container, Rear View**



**Photograph 57: Radiated Emissions – TC #5; Fiberglass Container, Front View**






**Photograph 58: Radiated Emissions – TC #5; Fiberglass Container, Rear View**



**Photograph 59: Radiated Emissions – TC #6; Fiberglass Container, Front View**






**Photograph 60: Radiated Emissions – TC #6; Fiberglass Container, Rear View**



**Photograph 61: Radiated Emissions – TC #7; Fiberglass Container, Front View**






**Photograph 62: Radiated Emissions – TC #7; Fiberglass Container, Rear View**



**Photograph 63: Radiated Emissions – TC #8; Fiberglass Container, Front View**






**Photograph 64: Radiated Emissions – TC #8; Fiberglass Container, Rear View**



**Photograph 65: Radiated Emissions – TC #9; Fiberglass Container, Front View**





**Photograph 66: Radiated Emissions – TC #9; Fiberglass Container, Rear View**

