Report No: 16061329HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Model: 0805



Report No: 16061329HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Back View)

Model: 0805



Report No: 16061329HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Model: 0805




Report No: 16061329HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Back View)

Model: 0805




Report No: 16061329HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Model: **0805**




Report No: 16061329HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Back View)

Model: **0805**



Report No: 16061329HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Model: 0805




Report No: 16061329HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Back View)

Model: **0805**




Report No: 16061329HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Model: 0805



Report No: 16061329HKG-001

Configuration Photographs

Worst-Case Radiated Emissions

(Back View)

Model: **0805**

