
Report No.: 17010646HKG-001 (FCC) 17010646HKG-002 (IC)

Equipment Photographs

Model: 0868

(Internal)






Report No.: 17010646HKG-001 (FCC) 17010646HKG-002 (IC)

Equipment Photographs

Model: 0868

(Internal)






Report No.: 17010646HKG-001 (FCC) 17010646HKG-002 (IC)

Equipment Photographs

Model: 0868

(Internal)






Report No.: 17010646HKG-001 (FCC) 17010646HKG-002 (IC)

Equipment Photographs

Model: 0868

(Internal)





Report No.: 17010646HKG-001 (FCC) 17010646HKG-002 (IC)

Equipment Photographs

Model: 0868

(Internal)







Report No.: 17010646HKG-001 (FCC) 17010646HKG-002 (IC)

Equipment Photographs

Model: 0868

(Internal)







Report No.: 17010646HKG-001 (FCC) 17010646HKG-002 (IC)

Equipment Photographs

Model: 0868

(Internal)






Report No.: 17010646HKG-001 (FCC) 17010646HKG-002 (IC)

Equipment Photographs

Model: 0868

(Internal)






Report No.: 17010646HKG-001 (FCC) 17010646HKG-002 (IC)

Equipment Photographs

Model: 0868

(Internal)







Report No.: 17010646HKG-001 (FCC) 17010646HKG-002 (IC)

Equipment Photographs

Model: 0868

(Internal)





Report No.: 17010646HKG-001 (FCC) 17010646HKG-002 (IC)

Equipment Photographs

Model: 0868

(Internal)

