



## Field Tune-up Procedure

04 December 2005

Attn: Reviewing Engineer  
Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

RE: Field Tuning Procedures  
FCC part 15C: OPA-TB 24-58, and OPA-TB 49  
FCC part 90Y: OPA-TB 49

The TB 24-58 and TB 49 radio with the above referenced FCC ID, have no field tunable adjustments. All configuration changes possible are made with either two rotary selector switches and/or via a software serial port as described in the User Manual for this equipment. Therefore there are no separate tuning procedures to submit.

Signatory,

A handwritten signature in black ink that reads "James R. Carlson".

James R. Carlson  
CEO and President  
Carlson Wireless Technologies Inc.