



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

May 17, 2004

RE: FCC ID: OU4-XWC900_ATCB001348
Attention: Mike Royer

I have a few comments on this Application.

1. Please note that you have provided the wrong test report. The report provided is for the XWS50M Motion Sensor. Please provide the report for the XWC900.
2. Please provide internal photos showing the tops and bottoms of all boards. Please disassemble the internal boards so this is possible.
3. Please provide the schematics for this device.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.