



APPENDIX 1: Photographs of test setup

Radiated Emission

Front



Rear




Worst Case Position (X-axis)

X-axis



Y-axis



Z-axis



*ECU and LF Initiator were separately checked at each position of all three axes X, Y, and Z.