

Sercomm Corporation中磊電子股份有限公司

Taipei Office: 8F, No.3-1, YuanQu St., NanKang, Taipei 115, Taiwan, R.O.C. TEL: 886-2-2655-3988 FAX: 886-2-2655-3966

DFS client device channel plan and software operational declaration

Date: 2021-01-18

We, Sercomm Corporation, declare that the device, FCC ID: P27XHB1 Model Name: XHB1xxxxxxxx; SCHB1AExxxxxxxxx (the 1st x should be "blank" or "-"; the rest x could be 0 to 9, A to Z, a to z, "blank" or "-", for marketing purpose), does not have Ad Hoc on "non-US frequencies" and/or on "DFS frequencies". Also, the client software and associated drivers will not initiate any transmission on DFS frequencies without initiation by a master. This includes restriction on transmissions for beacons and support for ad-hoc peer-to-peer modes.

Below is the channel / frequency plan for the device

CH	1	2	3	4	5	6	7	8	9	10	11
Frequency (MHz)	2412	2417	2422	2427	2432	2437	2442	2447	2452	2457	2462
Scan Type	Active										

5G band 1

СН	36	38	40	42	44	46	48
Frequency (MHz)	5180	5190	5200	5210	5220	5230	5240
Scan Type	Active						

5G band 2

СН	52	54	56	58	60	62	64
Frequency (MHz)	5260	5270	5280	5290	5300	5310	5320
Scan Type	Passive	Passive					

5G band 3

СН	100	102	104	106	108	110	112	116
Frequency (MHz)	5500	5510	5520	5530	5540	5550	5560	5580
Scan Type	Passive							
CH	132	134	136	140			-	
Frequency (MHz)	5660	5670	5680	5700				
Scan Type	Passive	Passive	Passive	Passive				

5G band 4

	CH	149	151	153	155	157	159	161	165
ſ	Frequency (MHz)	5745	5755	5765	5775	5785	5795	5805	5825
	Scan Type	Active							

Also, on DFS channels, the WLAN driver in the device operates under the control of an AP at all times, except when in ad-hoc mode on US non-DFS channels. The device passively scans DFS frequencies until a master device is detected. The control of this functionality is not accessible to anyone under any conditions. Furthermore, the firmware is protected by a special signature and CRC checksum. Signature and CRC checksum will be calculated and verified before firmware upgrade. Unauthorized modification to firmware will lead to the failure of verification and thus firmware upgrade will not be allowed. Sincerely yours,



Sercomm Corporation中磊電子股份有限公司

Taipei Office: 8F, No.3-1, YuanQu St., NanKang, Taipei 115, Taiwan, R.O.C. TEL: 886-2-2655-3988 FAX: 886-2-2655-3966

.....

Sercomm Corporation Nick Wu/ Engineer

TEL: 886-2-2655-3988*2556 FAX: 886-2-2655-3965

E-mail: Nick_wu@sercomm.com