

EMC Department

TEST REPORT No. 555/1009 Page 65 of 72 Issue Date: 17-02-2003

Test of: Raymarine Ltd. Pathfinder RL89CRC PLUS and RL811CRC PLUS FCC Part 80: 1998 and FCC Part 2: 1998




Graph OBW/555/1009/01




EMC Department

TEST REPORT No. 555/1009 Page 66 of 72 Issue Date: 17-02-2003

Test of: Raymarine Ltd. Pathfinder RL89CRC PLUS and RL811CRC PLUS FCC Part 80: 1998 and FCC Part 2: 1998




Graph OBW/555/1009/03




EMC Department

TEST REPORT No. 555/1009 Page 67 of 72 Issue Date: 17-02-2003

Test of: Raymarine Ltd. Pathfinder RL89CRC PLUS and RL811CRC PLUS FCC Part 80: 1998 and FCC Part 2: 1998




Graph OBW/555/1009/05




EMC Department

TEST REPORT No. 555/1009 Page 68 of 72 Issue Date: 17-02-2003

Test of: Raymarine Ltd. Pathfinder RL89CRC PLUS and RL811CRC PLUS FCC Part 80: 1998 and FCC Part 2: 1998




Graph OBW/555/1009/07




EMC Department

TEST REPORT No. 555/1009 Page 69 of 72 Issue Date: 17-02-2003

Test of: Raymarine Ltd. Pathfinder RL89CRC PLUS and RL811CRC PLUS FCC Part 80: 1998 and FCC Part 2: 1998




Graph OBW/555/1009/09




EMC Department

TEST REPORT No. 555/1009 Page 70 of 72 Issue Date: 17-02-2003

Test of: Raymarine Ltd. Pathfinder RL89CRC PLUS and RL811CRC PLUS FCC Part 80: 1998 and FCC Part 2: 1998




Graph OBW/555/1009/11




EMC Department

TEST REPORT No. 555/1009 Page 71 of 72 Issue Date: 17-02-2003

Test of: Raymarine Ltd. Pathfinder RL89CRC PLUS and RL811CRC PLUS FCC Part 80: 1998 and FCC Part 2: 1998




Graph OBW/555/1009/13



EMC Department

TEST REPORT No. 555/1009 Page 72 of 72 Issue Date: 17-02-2003

Test of: Raymarine Ltd. Pathfinder RL89CRC PLUS and RL811CRC PLUS FCC Part 80: 1998 and FCC Part 2: 1998



Graph OBW/555/1009/15

