



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

October 19, 2002

RE: THE LINKSYS GROUP, INC.

FCC ID: PKWBEFW11S4V3

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The block diagram should show the frequency of all oscillators in the RF portion of the device (CFR 2.1033(a)(5)).
- 2) Please supply a higher resolution photograph of the top of the board. Also, please add an additional photograph of the RF portion of the circuitry.

Timothy R. Johnson  
Examining Engineer

Direct Phone: 404-414-8071

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.