

In

To: "Timothy R. Johnson" <tjohnson@AmericanTCB.com>
Subject: =?big5?B?pl6rSKFHIFVSR0VOVCwgT1VUU1RBTkRJTkcgSVNTVUVTLi4uLi4u?=
=?us-ascii?Q?---=3E_Linksys?= Group, FCC ID: PKW-WAP51AB

Dear Tim,

For Item 1), Revised users manual has been submitted to your folder.
questions 2 & 3 have been answered

Item 4), Yes, this device was tested under fully configured.

Item 5), refer to test report page 5 & 10,

item 6), both transmitters will not be operated
simultaneously by the software control.

item 7), no need to consider the co-location problem as
they will not be operated simultaneously.

item 8,9,10) Turbo mode is not available in this device.

item 11), refer to test report page 81,

item 12), refer to the revised manual page 6,

item 13), refer to test report page 97-100.

Revised test reports and user manual were uploaded!

Thanks,

Regards,

Vivi