



2001.07.13

To : Mike Kuo
From : DXO Telecom CO., LTD

Subject : The contents of modification to meet the FCC Requirement.

We, DXO Telecom, confirm following modification from current test sample to meet FCC requirement.

Product : ADSL Modem

Model : XV1000

FCC ID : PPYXV1000

[Modification Details]

1. Copper tape (6 points)

Please refer to the photo of XV1000 to check the points. 4 copper tapes are applied on component side and 2 copper tapes are applied on solder side

2. By-pass capaitors (10 points)

Please refer to the photo of XV1000 to check the points. By-pass capacitors are apllied near L12, OSC1, J4, L1, L2 and L4 on component side. The other By-pass capacitors are located on the solder side.

This modification will be applied in production.

Please check EMI test report to find the point of modification.

DXO Telecom CO., LTD.

Un-Pyo Hong

A handwritten signature in black ink, appearing to read 'Un-Pyo Hong', positioned below the typed name.

