


FCC And Canadian Certification Report
2001218 / QRTL01-227 / QRTL01-228




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 24: FRONT OF TRANSMITTER PCB




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 25: BACK OF TRANSMITTER PCB IN CHASSIS




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 26: BACK OF TRANSMITTER PCB




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>




PHOTOGRAPH 27: BACK OF RECEIVER PCB IN CHASSIS



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>




PHOTOGRAPH 28: BACK OF RECEIVER PCB



PHOTOGRAPH 29: FRONT OF RECEIVER PCB IN CHASSIS



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 30: FRONT OF RECEIVER PCB