

6th January 2006

RFI Global Ltd
Ewhurst Park
Ramsdell
Basingstoke
Hampshire
RG26 5RQ


Dear Sir/Madam

FCC Submission PW9DA58233 – Changes

The Changes that have been implemented on the DA5823-033 for this permissive change are:

- RF Mixer redesign due to component obsolescence of TR3
- IC1, IC2 and IC4 Op-amps replaced with a single quad op-amp
- C38 and C39 removed from the micro's oscillator
- C44 and C45 decoupling capacitors removed to increase communication speed.
- Several other decoupling capacitors added and removed to circuit change.

Yours Sincerely



Samantha Ridler BEng MIEE
Compliance Engineer