



3301 E. Deseret Drive
St. George, Utah 84790
wilsonelectronics.com
cellular@wilsonelectronics.com

Phone 1-800-204-4104 Fax 1-435-656-2432

July 15, 2013

Tuning and Adjustment of Wilson Model 460001 Signal Booster

There are no external tuning adjustments. The amplifier is factory set to not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Sincerely,

A handwritten signature in black ink, appearing to read 'Patrick L. Cook', written in a cursive style.

Patrick L. Cook
Senior Research and Development Engineer