



3301 East Deseret Drive
St. George, Utah 84790
www.wilsonelectronics.com
info@wilsonelectronics.com

Phone 800.204.4104 • Fax 435.656.2432

July 20, 2013

Tuning and Adjustment of Wilson Model 460002 Signal Booster

There are no external tuning adjustments. The amplifier is factory set to not exceed maximum gains, power levels, or downlink dependent region (RSSI) as provided in the test results.

Sincerely,

A handwritten signature in black ink, appearing to read 'Patrick L. Cook', is written in a cursive style.

Patrick L. Cook
Senior Research and Development Engineer