



3301 E. Deseret Drive, St. George, UT 84790
www.wilsonelectronics.com • info@wilsonelectronics.com
phone 1-800-204-4104 • fax 1-435-656-2432

November 1, 2013

Tuning and Adjustment of Wilson Model 460005 Signal Booster

There are no external tuning adjustments. The amplifier is factory set to not exceed maximum gains, power levels, or downlink dependent region (RSSI) as provided in the test results.

Sincerely,

A handwritten signature in black ink, appearing to read 'Patrick L. Cook', written in a cursive style.

Patrick L. Cook
Senior Research and Development Engineer