

3301 E. Deseret Drive, St. George, UT 84790 www.wilsonelectronics.com • info@wilsonelectronics.com phone 1-800-204-4104 • fax 1-435-656-2432

January 5, 2017

Tuning and Adjustment of Wilson Model 460037 Signal Booster

There are no external tuning adjustments. The amplifier is factory set to not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Sincerely,

Patrick L. Cook

Chief Technology Officer