


Report No.: STS2011137

## APPENDIX-PHOTOGRAPHS OF EUT CONSTRUCTIONAL DETAILS

Model: Windy Plus Photo 1



Photo 2





Page 2 of 5 Report No.: STS2011137





Photo 4





Page 3 of 5 Report No.: STS2011137




Photo 6





Page 4 of 5 Report No.: STS2011137



Photo 8





Page 5 of 5 Report No.: STS2011137



Photo 10

