


## Annex A Photographs of the test setup

Photo documentation:

Photo 1: chamber C



Photo 2: chamber C



2011-02-15 Page 79 of 98



Photo 3: chamber C



Photo 4: chamber C



2011-02-15 Page 80 of 98



Photo 5: AC conducted



Photo 6: chamber F



2011-02-15 Page 81 of 98


## Test report no.: 1-2977-06-06/11



Photo 7: chamber F



Photo 8: chamber F



2011-02-15 Page 82 of 98