

Change description for a C2P

The antenna was changed in order to simplify the production process.

The EIRP is lower in all channels and for both radios (WLAN and GPRS)

The radiated power for all radios is now lower therefore only the radiated power and the SAR could be affected and were re-measured

Power measured:

| Device | Channel | Previous EIRP | New EIRP |
|----------|---------|---------------|----------|
| | | (dBm) | (dBm) |
| 802.11 | 1 | 20.72 | 17.89 |
| 802.11 | 6 | 21.07 | 19.31 |
| 802.11 | 11 | 21.87 | 20.39 |
| GSM 1900 | 512 | 31.5 | 27.3 |
| GSM 1900 | 661 | 32.0 | 27.2 |
| GSM 1900 | 810 | 32.4 | 27.17 |

CETECOM Inc. 411 Dixon Landing Road Milpitas, CA 95035 U.S.A. Phone: + 1 408 586 6200 Fax: + 1 408 586 6299 e-mail: info@cetecomusa.com URL: www.cetecom.com