




**Equipment Photographs**

**(Internal)**





**Equipment Photographs**

**(Internal)**





**Equipment Photographs**

**(Internal)**



Equipment Photographs

(Internal)





---


# INTERTEK TESTING SERVICE

---

Report No.: HK18050352

## Equipment Photographs

(Internal)



---


# INTERTEK TESTING SERVICE

---

Report No.: HK18050352



## Equipment Photographs

(Internal)



**Equipment Photographs**



**(Internal)**







**Equipment Photographs**

**(Internal)**



Equipment Photographs

(Internal)



---


# INTERTEK TESTING SERVICE

---

Report No.: HK18050352

## Equipment Photographs

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK18050352

## Equipment Photographs

(Internal)



---



# INTERTEK TESTING SERVICE

---

Report No.: HK18050352

## Equipment Photographs

(Internal)



---

# INTERTEK TESTING SERVICE

---

Report No.: HK18050352



## Equipment Photographs

(Internal)



**Equipment Photographs**

**(Internal)**




# INTERTEK TESTING SERVICE

Report No.: HK18050352

## Equipment Photographs

(Internal)





Equipment Photographs

(Internal)

