



Dear sir:

I am sorry to inform you that we have some typing error in the test report of FCC ID: Q87-WRT54GSV7, the mistake is on page 6 and 7 as below.

Adapter 3:

<b>Brand:</b>	LINKSYS
<b>Model:</b>	LS120V05AE → <b>100~240Vac</b>
<b>Input:</b>	120~240Vac, 50/ 60Hz , 0.5A
<b>Output:</b>	12Vdc, 500mA
<b>Power Cord:</b>	DC: 1.8m shielded cable without core AC: 0.5m shielded cable without core

→ **DC: 1.8m non shielded cable without core  
AC: 0.5m non shielded cable without core**

Adapter 4:

<b>Brand:</b>	LINKSYS
<b>Model:</b>	LS120V05A → <b>100~240Vac</b>
<b>Input:</b>	120~240Vac, 50/ 60Hz , 0.5A
<b>Output:</b>	12Vdc, 500mA
<b>Power Cord:</b>	DC: 1.8m shielded cable without core AC: 0.5m shielded cable without core

→ **DC: 1.8m non shielded cable without core  
AC: 0.5m non shielded cable without core**

I am really apologized for this mistake, would you please exchange the test report on the FCC web.

Thanks for your kind assistance.

Best Regards,  
 Stephanie Hung (洪樹薇)  
 Advance Data Technology Corporation (誠信科技)  
 Tel: 886-3 318 3232 Ext. 1668  
 e-mail: [stephanie@adt.com.tw](mailto:stephanie@adt.com.tw)