


ANNEX B INTERNAL PHOTOS

The labelling was wrong during the tests and corrected by the customer.
See also chapter 3 of the report for more information.



124226_1.JPG: EUT, top view

ANNEX B INTERNAL PHOTOS




124226_2.JPG: EUT, bottom view

ANNEX B INTERNAL PHOTOS




124226_3.JPG: EUT, top view with antenna connector

ANNEX B INTERNAL PHOTOS



124226_5.JPG: Connector board, bottom view

ANNEX B INTERNAL PHOTOS



124226_6.JPG: Connector board with mounted carrier board and EUT, top view