

 Prüfbericht - Nr.:
 50302721 001
 Seite 36 von 40


 Test Report No.
 Page 36 of 40

7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View 1)



Photograph 2: Set-up for Spurious Emissions (Front View 2)






Produkte Products

Prüfbericht - Nr.: 50302721 001


Seite 37 von 40 *Page 37 of 40*

Test Report No.

Photograph 3: Set-up for Spurious Emissions (Back View 1)



Photograph 4: Set-up for Spurious Emissions (Back View 2)








 Prüfbericht - Nr.:
 50302721 001
 Seite 38 von 40

 Test Report No.
 Page 38 of 40

Photograph 5: Set-up for Conducted testing (View 1)



Photograph 6: Set-up for Conducted testing (View 2)





 Prüfbericht - Nr.:
 50302721 001
 Seite 39 von 40

 Test Report No.
 Page 39 of 40

Photograph 7: Set-up for Mains Conducted testing (Front View)



Photograph 8: Set-up for Mains Conducted testing (Back View)

